


April 21, 1987

TO: File

FROM: Frank J. Filas, Reclamation Engineer 

RE: Site Inspection, DOE/019/027, Jonny Trujillo, Caboose #1-#12

Frank Filas inspected this abandoned mine site on April 13, 1987. Conditions were similar to what was described on the January, 1979 inspection. Three open portals and several small waste piles exist onsite. There are numerous unplugged drill holes on top of the hillcrest above the wash. No claim markers were observed.

The area is environmentally stable, and the open portals represent a minimum risk to the public due to the remote location. It appears that the operation stayed under two acres of total disturbance.

clj  
1115R/86